

## GILLMORESPACE Seconds

Prices do not include delivery and payment terms are pro forma. Use the 'quick browse' menu on the website if you need to identify these designs by range.

Email or fax your order requirements to charles@gillmorespace or 0845 373 2764. Where noted photos of the fault can be supplied by email on request.

Product Code	Product Description	Description of fault	Grade	Photo?	Retail (ex VAT)	Clearance price (ex VAT)	Product ID
A505-6301	Cheval mirror - Pritchard	Ex display. No obvious defects.	A2	No	£156.00	£79.00	SH
A505-6301	Cheval mirror - Pritchard	Metal finish scarred on one corner of metal base caused in transit. Very, very small scratch on glass which is very difficult to find.	B1	Yes	£156.00	£49.00	260410-3
D420-6805	Square sideboard - Vico	A few scuffs, doors not closing properly. No carton	B1	No	£490.50	£144.00	291009-c
D420-6805	Square sideboard - Vico	Factory seconds due to wrong specification and mounting of Hafele hinges on doors (not noticeable when doors are closed). Packaged and sealed as new. <b>3 available as at 13-7. Priced to clear at over half RRP - FANTASTIC OFFER!</b>	A2	Yes	£490.50	£199.00	251109-b
D420-6805	Square Sideboard - Vico	Bruise on lower corner by foot, the laquer on one door is a bit inconsistant	B1	Yes	£490.50	£149.00	181201-a
D420-6805	Square Sideboard - Vico	Very small mark/graze on lower right corner caused by mishandling. Unfortunately the impact has caused the doors to become misaligned which will need adjusting on the hinges or possibly re-hanging. Straightforward task for compentent DIY'er. Otherwise unit in v good condition	B1	Yes	£490.50	£129.00	040810-1
D420-6805	Square Sideboard - Vico	Ex display model in perfect condition except the doors have become fractionally misaligned. Hinges need adjusting which is an easy job for anyone with competent DIY skills	A2	Yes	£490.50	£199.00	040810-2
D421-6805	Low sideboard - Vico	Return from customer due to change of mind. Very, very small mark on top surface caused when the item was re-packaged by the customer. Currently being used as a showroom piece. Great condition - excellent value!	A2	No	£512.50	£239.00	SH
D423-6807	Square sideboard - Lucienne White	Impact in transit has caused a bruise/cracked lacquer on the front edge of the top left door about 5cm long. This impact has also slightly deformed the hinges meaning the doors are not aligned and do not close smoothly. A competent DIY'er would be able to either repair the hinges or re-hang the doors on new hinges. A spare alternative full set of hinges is supplied.	B2	Yes	£486.50	£50.00	110610-1
L112-6805	Coffee table - Vico	Small bruising on two corners due to handling impact. Could be touched up. <b>Priced to clear</b>	B2	Yes	£173.25	£29.00	291009-p
L112-6805	Coffee table - Vico	Small bruising on two corners due to handling impact. Could be touched up. <b>Priced to clear</b>	B2	Yes	£173.25	£39.00	150310-3
L112-6805	Coffee table - Vico	Tiny bruis on one corners due to handling impact. Could be touched up. <b>Priced to clear</b>	B2	Yes	£173.25	£34.00	050710-3
L125-7503	Coffee table - loopy oak	Impact bruise in transit on lowest edge. Not easily noticed. Good value second	B1	Yes	£339.00	£119.00	110610-2
L127-7506	Loopy table - white	Miss handling in transit has casued an impact bruise on one edge	B1	Yes	£295.00	£119.00	290110-6
L131-8308	Coffee table - Raft	Ex display, no noticeable defects. <b>Great value!</b>	A2	No	£251.50	£79.00	SH
L131-8308	Coffee table - Raft	Small bruising on two corners due to handling impact. Could be smoothed off. <b>Priced to clear!</b>	B2	Yes	£173.25	£10.00	050710-1

## GILLMORESPACE Seconds

Product Code	Product Description	Description of fault	Grade	Photo?	Retail (ex VAT)	Clearance price (ex VAT)	Product ID
L131-8308	Coffee table - Raft	Very small bruising on one corner due to handling impact (could be smoothed off). Very faint greyish mark on veneer - hardly noticeable. <b>Priced to clear!</b>	B1	Yes	£173.25	<b>£23.00</b>	050710-2
L319-3306	Table - Barcelona Walnut	The veneer on the two drawers fronts does not match - the veneer on the right hand drawer is lighter. Both drawers are slightly unaligned from the top surface.	B1	Yes	£382.00	<b>£119.00</b>	190210-2
L319-3306	Table - Barcelona Walnut	Customer return due to change of mind (nothing wrong with unit). However it was not properly re-packaged and has suffered return transit damage. Carious scuff marks caused by cardboard rubbing on lacquer, small dink (about 5p size) on front drawer edge. Missing 1 screw on underside of frame (not seen) due to burred thread.	B1	Yes	£382.00	<b>£119.00</b>	040810-3
L319-3306	Table - Barcelona Walnut	Both drawers loose from runners. Repairable, Bruise on one corner	B1	Yes	£382.00	<b>£60.00</b>	291009-a
L320-3307	Table - Barcelona White	Substandard factory delivery to clear packaged and sealed as new. Minor faults (not exclusive to all) include dirty prints on surface, drawer insides poorly finished (not noticed when closed), excess paint build up noticed on some edges/corners, awkward/time consuming assembly. <b>Good value for the price, only 6 left.</b>	A2	Yes	£369.00	<b>£139.00</b>	241109-c
L320-3307	Consol table - Barcelona white	Impact bruises (finger nail size) on each of the lower front corners	B1	Yes	£369.00	<b>£109.00</b>	180610-sh
L322-6807	Console Table - mondrian black	Ex display, no noticeable defects	A2	No	£303.75	<b>£149.00</b>	SH
L323-6807	Low sideboard - Lucienne white	Missing door hinge. Various marks on paintwork due to excessive handling. Indent in lower front drawer (photo). Inconsistent paint finish on side panel. <b>Priced to clear!</b>	B2	Yes	£556.00	<b>£89.00</b>	191009-f
L323-6807	Low sideboard - Lucienne white	Two minor scuffs on white lacquer.	B1	Yes	£556.00	<b>£199.00</b>	290110-1
L539-8308	Single open unit - Ivy Black	Transit damage has caused panel fracture near fitting joint	B2	Yes	£173.25	<b>£49.00</b>	091109-F
L520-8308	Square sideboard - Ivy Black - handles black	Noticeable hairline scratch on top surface. Otherwise good with excellent price	B1	Yes	£460.25	<b>£149.00</b>	291009-j
L531-8308	Low sideboard - Ivy Black - handles black	Uneven surface in very small area just above joint fitting (see photo). Good value	B1	Yes	£395.00	<b>£169.00</b>	191009-m
L531-8308	Low sideboard - Ivy Black - handles black	Very small (about fingernail size) impact damage on corner caused by miss-handling in transit	B1	Yes	£395.00	<b>£149.00</b>	190210-1
L531-8308	Low sideboard - Ivy Black - handles black	Ex display, no noticeable defects	A2	No	£395.00	<b>£179.00</b>	SH
L623-8309	Small floating shelf - Ivy White	Ex display, no noticeable defects	A3	No	£47.25	<b>£14.00</b>	110610-3
L623-8310	Small floating shelf - Ivy White	Ex display, no noticeable defects	A4	No	£47.25	<b>£14.00</b>	110610-4
L625-8308	Small floating shelf - Ivy Black	Ex display, no noticeable defects	A2	No	£47.25	<b>£19.00</b>	131109-E
S150-6201	Kingsize Bed - Brompton	Missing hardware - spares probably available to make complete set. A1 condition	A2	No	£599.50	<b>£199.00</b>	SH

## GILLMORESPACE Seconds

Product Code	Product Description	Description of fault	Grade	Photo?	Retail (ex VAT)	Clearance price (ex VAT)	Product ID
S221-3101(R)	Bedside chest - Barcelona walnut	Scuff marks on top surface. Right hand opening.	B1	No	£190.75	£59.00	291009-i
S221-3101(L)	Bedside chest - Barcelona walnut	Missing two black plastic caps for the metal feet, otherwise perfect. Left hand opening	A2	Yes	£190.75	£89.00	190210-5
S221-3101R	Bedside chest - Barcelona walnut	Small dink on top left corner of the door which is hardly seen. The door is misaligned (can be re-adjusted). 2 plastic caps are missing from the feet. Right hand opening	B1	Yes	£190.75	£59.00	190210-3
S232-3704L	Bedside chest - Barcelona white	Door hinges have pulled away from the cabinet - repairable.	B2	No	£190.75	£34.00	020909-J
S232-3704L	Bedside chest - Barcelona white	Chipped inside door surface, otherwise very good	A2	No	£177.75	£82.00	020909-H
S232-3704L	Bedside chest - Barcelona white	Hairline crack along top left mitre edge. Magnetic pads (enclosed) need to be applied	B1	No	£177.75	£69.00	291009-g
S302-6205	Wardrobe - Brompton	Poor selection of veneer which has resulted in uneven surface on one area (noticable only in certain light). Tiny bruise mark caused in transit. Exposed glue in a couple of small areas.	A2	Yes	£843.00	£299.00	290110-2
Last updated	04/08/2010						