

## GILLMORESPACE Seconds

Prices do not include delivery and payment terms are pro forma. Use the 'quick browse' menu on the website if you need to identify these designs by range.

Email or fax your order requirements to [charles@gillmorespace](mailto:charles@gillmorespace) or 0845 373 2764. Where noted photos of the fault can be supplied by email on request.

Product Code	Product Description	Description of fault	Grade	Photo?	Retail (ex VAT)	Clearance price (ex VAT)	Product ID
D420-6805	Square sideboard - Vico	A few scuffs, doors not closing properly. No carton	B1	No	£490.50	£144.00	291009-c
D420-6805	Square sideboard - Vico	Substandard factory delivery due to wrong spec of door hinges and poor application of hinges into carcass (not noticeable when doors are closed). Packaged and sealed as new. <b>Only 3 available</b>	A2	Yes	£490.50	£199.00	251109-b
D420-6805	Square sideboard - Vico	Customer return. Door hinges need a bit of tuning otherwise OK	B1	No	£490.50	£159.00	291009-d
D420-6805	Square Sideboard - Vico	Bruise on lower corner by foot, the laquer on one door is a bit inconsistent	B1	Yes	£490.50	£199.00	181201-a
L102-3704	Coffee table - Manuel	Ex display, no noticeable defects. Excellent value	A2	No	£239.00	£69.00	SH
L112-6805	Coffee table - Vico	Small bruising on two corners due to handling impact. Could be touched up. <b>Priced to clear</b>	B2	Yes	£173.25	£29.00	291009-p
L127-7505	Loopy table - white	Several marks and bruises caused by transit damage plus weakened structural joint	B2	Yes	£295.00	£69.00	220110-2
L127-7506	Loopy table - white	Tiny laquer imperfection (pin head size) plus 2 bruises from impact damage	B2	Yes	£295.00	£99.00	220110-3
L127-7506	Loopy table - white	Miss handling in transit has casued an impact bruise on one edge	B1	Yes	£295.00	£119.00	290110-6
L127-7506	Loopy table - white	2 large areas of surface cracking. Inside garzing of the paintwork has occured due to movement of loose hardware inside the box during transit	B2	Yes	£295.00	£49.00	190210-4
L131-8308	Coffee table - Raft	Ex display, no noticeable defects. <b>Great value</b>	A2	No	£251.50	£79.00	SH
L221-6805	Side table - mondrian RED GLASS	Ex display, no noticeable defects	A2	No	£173.25	£39.00	SH
L230-8308	Nest of tables - Fritz	Substandard factory delivery due to poor metal finishing.	B1	Yes	£424.80	£124.00	SH
L230-8308	Nest of tables - Fritz	Substandard factory delivery due to poor metal finishing. Packaged and sealed as new. <b>Only 3 available priced to clear - excellent value</b>	B1	Yes	£424.80	£139.00	251109-c
L319-3306	Console table - Barcelona walnut	Left hand drawer unattached from runner, right drawer front loose. Repairable	B2	No	£382.00	£99.00	020909-N
L319-3306	Table - Barcelona Walnut	Customer return. No obvious defect.	B1	No	£382.00	£149.00	291009-m

## GILLMORESPACE Seconds

Product Code	Product Description	Description of fault	Grade	Photo?	Retail (ex VAT)	Clearance price (ex VAT)	Product ID
L319-3306	Table - Barcelona Walnut	Both drawers loose from runners. Repairable, Bruise on one corner	B1	Yes	£382.00	£60.00	291009-a
L319-3306	Table - Barcelona Walnut	Customer return. No obvious defect.	B1	No	£382.00	£149.00	131109-H
L319-3306	Table - Barcelona Walnut	The veneer on the two drawers fronts does not match - the veneer on the right hand drawer is lighter. Both drawers are slightly unaligned from the top surface.	B1	Yes	£382.00	£119.00	190210-2
L320-3307	Table - Barcelona White	Substandard factory delivery to clear packaged and sealed as new. Minor faults (not exclusive to all) include dirty prints on surface, drawer insides poorly finished (not noticed when closed), excess paint build up noticed on some edges/corners, awkward/time consuming assembly. <b>Good value for the price, only 6 left.</b>	A2	Yes	£369.00	£139.00	241109-c
L322-6807	Console Table - mondrian black	Ex display, no noticeable defects	A2	No	£303.75	£149.00	SH
L323-6807	Low sideboard - Lucienne white	Missing door hinge. Various marks on paintwork due to excessive handling. Indent in lower front drawer (photo). Inconsistent paint finish on side panel	B2	Yes	£556.00	£99.00	191009-f
L323-6807	Low sideboard - Lucienne white	Drop down door doesn't close tight which is fixable. Otherwise in perfect condition	B1	No	£556.00	£249.00	051109-B
L323-6807	Low sideboard - Lucienne white	Two minor scuffs on white lacquer.	B1	Yes	£556.00	£199.00	290110-1
L532-8308	Low sideboard - Ivy White - handles white	This is a customer return due to change of mind. But the item has clearly been used as there are three faint marks (each the size of a small finger nail) on the top surface which must have been left by the rubber feet of an appliance. There is also a very faint scuff mark.	B1	Yes	£373.25	£109.00	290110-5
L539-8308	Single open unit - Ivy Black	Transit damage has caused panel fracture near fitting joint	B2	Yes	£173.25	£49.00	091109-F
L523-8308	Square sideboard - Ivy Black - handles white	Noticeable hairline scratch on top surface. Otherwise good with excellent price	B1	Yes	£460.25	£149.00	291009-j
L531-8308	Low sideboard - Ivy Black - handles white	Uneven surface in very small area just above joint fitting (see photo). Good value	B1	Yes	£395.00	£169.00	191009-m
L531-8308	Low sideboard - Ivy Black - handles white	Very small (about fingernail size) impact damage on corner caused by miss-handling in transit	B1	Yes	£395.00	£149.00	190210-1
L531-8308	Low sideboard - Ivy Black - handles white	Ex display, no noticeable defects	A2	No	£395.00	£199.00	SH
L625-8308	Small floating shelf - Ivy Black	Ex display, no noticeable defects	A2	No	£47.25	£19.00	131109-E
L817-3306	Stool - Jasper black	Ex display, no noticeable defects	A2	No	£129.75	£54.00	SH
L822-8308	Side Table - Enzo Cylinder leather white	Ex display, no noticeable defects	A2	No	£138.50	£64.00	SH
S150-6201	Kingsize Bed - Brompton	Missing hardware - spares probably available to make complete set. A1 condition	A2	No	£599.50	£299.00	SH

## GILLMORESPACE Seconds

Product Code	Product Description	Description of fault	Grade	Photo?	Retail (ex VAT)	Clearance price (ex VAT)	Product ID
S153-3101	Double bed - Barcelona Walnut	Customer return due to missing screw sleeves in headboard. Replacements have since been installed and the product will now assemble	A2	No	£516.75	£199.00	191009-a
S153-3101	Double bed - Barcelona Walnut	Pre-drilled screw sleeve holes are missing from the headboard (could be overcome by competent DIYer). The footboard also has glue spills/stains over the top of it and one of the side panels has a small dink taken out of it.	B2	No	£516.75	£99.00	110210-2
S156-3307	Double Bed - Barcelona White	One edge of the headboard component is missing its final lacquer coat. This can only be noticed by feeling the surface texture - there is no difference to the colour and the product therefore looks 100% perfect.	A2	No	£486.50	£199.00	291010-3
S219-6201	Bedside chest - Brompton	Slight movement in the carcass due to loose fittings, otherwise fine	A2	No	£164.75	£59.00	020909-B
S219-6201	Bedside cabinet - Brompton	Very slight mark on feet	A2	No	£164.75	£59.00	161009-a
S221-3101(L)	Bedside chest - Barcelona walnut	Missing two black plastic caps for the metal feet, otherwise perfect	A2	Yes	£190.75	£89.00	190210-5
S221-3101R	Bedside chest - Barcelona walnut	Ex display, no noticeable defects	A2	No	£190.75	£95.00	SH
S221-3101R	Bedside chest - Barcelona walnut	Small dink on top left corner of the door which is hardly seen. The door is misaligned (can be re-adjusted). 2 plastic caps are missing from the feet.	B1	Yes	£190.75	£59.00	190210-3
S232-3704L	Bedside chest - Barcelona white	Door hinges have pulled away from the cabinet - repairable.	B2	No	£190.75	£34.00	020909-J
S232-3704L	Bedside chest - Barcelona white	Chipped inside door surface, otherwise very good	A2	No	£177.75	£82.00	020909-H
S232-3704L	Bedside chest - Barcelona white	Hairline crack along top left mitre edge. Magnetic pads (enclosed) need to be applied	B1	No	£177.75	£69.00	291009-g
S232-3704R	Bedside chest - Barcelona white	Loose hinges - repairable. Slightly dirty inside.	B1	No	£177.75	£69.00	020909-D
S233-1704	Dresser - Portland	One drawer front profile is not straight due to movement in solid wood. Good value price.	B1	Yes	£599.50	£149.00	212
S243-6807	Bedside chest - Lucienne White	Small dent on lower left corner caused in transit	B1	Yes (205)	£260.25	£49.00	051109-C
S244-6807	Dresser and table - Lucienne White	Large bruise & scratch on top drawer & top table edge. Runner for table top has come unattached but are supplied. <b>Priced to clear!</b>	B2	Yes	£643.00	£49.00	091109-I
S244-6807	Dresser and table - Lucienne White	One foot has been wrenched off base and needs re-setting. Table top needs tightening to its base. <b>Priced to clear!</b>	B2	No	£643.00	£49.00	091109-J
S244-6807	Dresser and table - Lucienne White	Desk top needs tightening to its base. Slight damage to top edge (photo). Leather surface peeling on edge. Drawers not closing properly.	B2	Yes	£643.00	£59.00	131109-B
S244-6807	Dresser and table - Lucienne White	Customer return due to light surface scratches on top surface of extension component. These are only noticeable on close inspection.	B1	Yes	£643.00	£199.00	180110-1

## GILLMORESPACE Seconds

Product Code	Product Description	Description of fault	Grade	Photo?	Retail (ex VAT)	Clearance price (ex VAT)	Product ID
S302-6205	Wardrobe - Brompton	Poor selection of veneer which has resulted in uneven surface on one area (noticeable only in certain light). Tiny bruise mark caused in transit. Exposed glue in a couple of small areas.	A2	Yes	£843.00	£349.00	290110-2
Last updated	19/02/2010						