







<p>A</p>  <p>M8*20</p> <p>X12</p>	<p>B</p>  <p>M5</p> <p>X1</p>
<p>C</p>  <p>316-115</p> <p>X4</p>	<p>D</p>  <p>316-103</p> <p>X1</p>



IMPORTANT - When lifting the unit into its upright position DO NOT pivot it on its legs.

